## Freedom of Information Request FOI 24-377

## Number of Reported Engine Piston Failures for Toyota Prado 120-series and 150-series

As part of its work administering the <u>Road Vehicle Standards (RVS) legislation</u>, the Department of Infrastructure, Transport, Regional Development, Communications and the Arts (the Department) maintains databases of <u>reports</u> since 2016 submitted by members of the public, industry and other regulators regarding potential vehicle safety issues or alleged non-compliance with RVS legislation.

This document provides the number of such reports received by the Department of engine failures involving cracked pistons for Toyota Prado 120-series and 150-series cars.

Table 1: Number of Toyota Prado Reported Cracked Piston Engine Failures by Model.

Model	Number of Reported Cracked Piston Engine Failures
Toyota Prado 120-series	2
Toyota Prado 150-series	0
Toyota Prado, model not specified	3