

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 28/05/2024 – 2/06/2024

SYDNEY AIRPORT

There were no approved dispensations for Sydney Airport during this period.

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 28/05/2024 – 2/06/2024

There were no refused dispensations for Sydney Airport during this period.

Note: This Dispensation Report records all dispensations that are formally approved or refused. The Delegates regularly receive questions by phone from airlines about whether a dispensation is likely to be approved if an application is made.

Where the Delegate advises that an application is unlikely to be given if an application is made, airlines do not generally make a formal application.

These situations are not recorded in this Dispensation Report.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 28/05/2024 – 2/06/2024

ADELAIDE AIRPORT

DETAILS OF DISPENSATION

Date: 28 May 2024

Aircraft: A320

Registration: VH-YXS

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ805 (Sunshine Coast Airport to Adelaide) was delayed arriving at Adelaide Airport due to a bird strike by the aircraft on arrival at Sunshine Coast Airport. An engineer travelled from Brisbane to complete an engineering report before departure could be approved. A dispensation was granted for landing no later than 23:50 local time. JQ805 had 148 passengers including 11 children, 1 infant, 2 wheelchair users, and 6 crew on-board. The aircraft arrived at 23:10 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

APPROVED DISPENSATIONS

INDIVIDUAL DISPENSATION DETAILS FOR PERIOD: 28/05/2024 – 2/06/2024

GOLD COAST AIRPORT

DETAILS OF DISPENSATION

Date: 31 May 2024

Aircraft: A321

Registration: VH-VWT

Operator: Jetstar Airways

Operation: Arrival

Circumstances Leading to Request: Jetstar Airways flight JQ451 (Gold Coast to Melbourne) was delayed departing from Gold Coast Airport due to leak in the forward galley and oven requiring an engineering inspection to allow approval for departure. Further delays occurred when a return to bay was needed to offload an unruly passenger. A dispensation was granted for take-off no later than 23:50 local time. JQ451 had 171 passengers including 7 children and 8 crew on-board. The aircraft departed at 23:40 local time.

Approved: Yes

Reasons for Approval: The Delegate was satisfied that exceptional circumstances existed for issue of a curfew dispensation.

ESSENDON FIELDS AIRPORT

There were no approved dispensations for Essendon Fields Airport during this period.

REFUSED DISPENSATIONS

INDIVIDUAL REFUSED DISPENSATION DETAILS FOR PERIOD: 28/05/2024 – 2/06/2024

ADELAIDE AIRPORT

There were no refused dispensations for Adelaide Airport during this period.

GOLD COAST AIRPORT

There were no refused dispensations for Gold Coast Airport during this period.

ESSENDON FIELDS AIRPORT

There were no refused dispensations for Essendon Fields Airport during this period.

Note: This Dispensation Report records all dispensations that are formally approved or refused. The Delegates regularly receive questions by phone from airlines about whether a dispensation is likely to be approved if an application is made.

Where the Delegate advises that an application is unlikely to be given if an application is made, airlines do not generally make a formal application.

These situations are not recorded in this Dispensation Report.